

CLEANING INSTRUCTIONS FOR Tec 2000 product line including:

Tec 2000, Tec Satin, Tec 2000 Anti-Static, Tec 2000 Anti-Graffiti, Tec Fusion

CLEANING INSTRUCTIONS: The Tec 2000 product line surface is very hard and durable and will withstand minor impacts or scuffs without significant damage. It is important however, to keep the surface clean of chemical and dirt build-up that will attack the surface over time. The surface should be washed and kept clean with standard non-abrasive glass cleaning solutions, such as Windex or non-commercial spray cleaners, or other liquid cleaning methods. In some cases a solution of soapy water will remove common dirt and residue that builds up on the surface. **Do not** use excessive pressure when scrubbing, gentle washing should be sufficient. Abrasive pads or buffing compounds with grit should not be used on any of the Tec 2000 product line.

NOTE: Frequency of cleaning will depend on the exposure to contaminants. Generally speaking, the **Tec2000 product line** surface **should be** kept clean of dirt and chemicals.

Hexane or kerosene can be used to remove grease, oil and most other petroleum based products. These solvents may be obtained at a paint or hardware store and strict adherence should be used with manufacturer's recommendations.

Acceptable cleaners:

- Fantastik® Glass Plus ® Formula 409® Top Job® Mr. Clean®
- Windex® Window cleaner

NOTICE: *Tec 2000 product line surface should be cleaned on a regular basis. Depending on conditions, the frequency may vary. If coating is used outdoors, care must be taken to avoid buildup of soot, oil, road dirt, hard water deposits, and other chemicals that may damage the surface. Whenever possible, the Tec 2000 product line surface should be kept away from exposure to harsh weather conditions.*

For further information please call or email us at: (714) 547-5477 or <u>info@noxtat.com</u>