

NOTICE TO ALL PERSONS.
THE INSTRUCTIONS BELOW MUST
BE FOLLOWED IN NUMERICAL
ORDER.

THIS DOCUMENT IS ONLY FOR SCREENS WITH
LIFTING STRAPS INCLUDED.

1. Read all instructions thoroughly before opening the crate.
2. Before opening crate, inspect the crate thoroughly for any damage. Photograph and report any damage to the crate to your supplier immediately.
3. Ensure the area where the crate is setting, is a solid level surface and clear of any debris, hazards or obstructions.
4. Once the crate is in the immediate proximity of the install area, remove **ONLY** the perimeter screws of crate cover (marked in **red**).
5. Remove the crate cover ensuring that at no point does it come in contact with the screen itself. Any contact **WILL** cause damage to the screen. (Note: the screen box **is not** designed to be removed from its cradle).
6. Inspect the shock detector and tip n tell (they are placed inside the crate), to ensure that neither of them have been triggered. If one or both of them have been triggered, **STOP!!** Report this to your supplier immediately. If neither has been triggered then continue to step 7.
7. Remove installation package from crate.
8. Without removing the masking, inspect the screen itself for any visible damage. If there is any damage, **STOP!!** Photograph and report any and all damages to your supplier immediately. If there is no damage continue to step 9.
9. Remove frame blocking from the left and right side of the crate. The screws for these are on the outside of the crate, on the left and right sides. They are marked in **red**. There are two screws on each side.
10. Attach a lifting bar to the lifting straps on each side. **DO NOT** use a yoke or lift the screen by each individual strap. Lift the bar slowly, making sure while lifting it, that it remains level and does not turn from one side to the other.
11. Depending on the type of install, the blocking around the perimeter of the frame may need to be removed.
12. Once the screen is removed from the crate, proceed with site specific installation.